

Table 6-5
Power Transformer Assembly Wiring Harness⁴

PIN NO	COLOR	DESCRIPTION
1	BLACK	AC INPUT
2	BROWN	AC INPUT
3	RED	AC INPUT
4	YELLOW	AC INPUT
5	-	NOT USED
6	PINK/YEL	6.3 V _{rms}
7	PINK/YEL	6.3 V _{rms}
8	PINK/GRN	HV
9	PINK/GRN	HV
10	WHITE	18 V _{rms}
11	WHITE/RED	CENTER TAP
12	WHITE	18 V _{rms}
13	GRAY	130 V _{rms}
14	GRAY	130 V _{rms}

⁴ This harness mates with 1.A1.P7.